

General Information

Date & Time: 07, Dec, 2024 09:58

Make	Toyota	Model	Vios
YOM	2023	Mileage	6,597
Registration No.	NHI1855	Chassis No.	PA1B18F30P4203323
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	BLACKISH RED MICA		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	104.0	105	100	107
2	Boot Lid	100.0	102	98	100
3	Roof	95.4	112	90	83/97
4	Left Front Fender	96.6	97	94	99
5	Left Front Door	102.0	100	106	100
6	Center Panel Left				
7	Left Rear Door	106.3	100	118	101
8	Left Back Panel	107.4	114	110	98
9	Right Front Fender	97.9	104	93	97
10	Right Front Door	101.1	97	100	107
11	Center Panel Right				
12	Right Rear Door	162.0	250	103	133
13	Right Back Panel	282.0	197	201	448

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : A
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Missing - Yes / (R) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes / Rear Seat - Grime - Large	Remarks Trunk Hood, Rear Gate - Dent - Small / Rear Bumper, Lamps, Panels - Dent - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes

with spare tire/jack/warranty booklets/No reverse camera/ no tools