

General Information

Date & Time: 07, Dec, 2024 09:55

Make	Toyota	Model	Fortuner
YOM	2023	Mileage	9,213
Registration No.	CAZ7654	Chassis No.	MHFCB8GS9N0528550
CC	2.4	Transmission	A/T
Fuel Type	Diesel	Type of Body	SUV
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	107.1	103	121	97
2	Boot Lid	83.8	80	89	83
3	Roof	105.5	117	109	114/82
4	Left Front Fender	100.5	98	103	101
5	Left Front Door	81.9	77	86	83
6	Center Panel Left				
7	Left Rear Door	98.5	106	90	100
8	Left Back Panel	209.0	308	170	149
9	Right Front Fender	92.0	94	90	93
10	Right Front Door	81.5	88	78	78
11	Center Panel Right				
12	Right Rear Door	79.8	82	76	82
13	Right Back Panel	95.6	95	88	104

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Seat - Grime - Medium	Remarks (L) Rear Fender - Repair Traces - Yes / (L) Rear Fender, Molding - Repair mark - Yes / Front Bumper, Grille, Lamps - Repair mark - Yes / Front Bumper, Grille, Lamps - Crack, Gap - Medium / Rear Bumper, Lamps, Panels - Scratch & Dent - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
without tools/ with spare tire and warranty booklet/ no jack