


General Information

Date & Time: 14, Dec, 2024 12:05

Make	Toyota	Model	Innova
YOM	2022	Mileage	67,215
Registration No.	DAP2817	Chassis No.	PA2JA8EM8M0099314
CC	2.8	Transmission	A/T
Fuel Type	Diesel	Type of Body	MPV
Colour	BLACKISH RED MICA		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	112.0	118	111	107
2	Boot Lid	84.4	87	79	87
3	Roof	90.5	88	90	91/93
4	Left Front Fender	95.5	98	97	91
5	Left Front Door	96.7	99	99	92
6	Center Panel Left				
7	Left Rear Door	96.7	95	98	97
8	Left Back Panel	103.0	103	103	103
9	Right Front Fender	99.6	99	100	100
10	Right Front Door	103.3	100	103	107
11	Center Panel Right				
12	Right Rear Door	102.3	105	101	101
13	Right Back Panel	108.6	104	109	113

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Medium / Overall Interior - Smell - Yes / (L) Front Trim - Grime - Medium / (L) Front Seat - Grime - Medium / Rear Seat - Grime - Medium	Remarks (R) Rear Door, Molding - Scratch & Dent - Large / (R) Front Door, Molding - Scratch & Dent - Large / (R) Front Fender, Molding - Dent - Small / (R) Rear Fender, Molding - Dent - Minimal / (L) Rear Door, Molding - Scratch & Dent - Medium / (L) Front Door, Molding - Scratch & Dent - Small / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / Bonnet, Headlight - Scratch - Small / Front Bumper, Grille, Lamps - Scratch & Dent - Large
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes

no warranty booklet, tools and jack. with user manual. wet carpet.