

General Information

Date & Time: 04, Oct, 2025 14:15

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	10,128
Registration No.	CCA8304	Chassis No.	PA1B18F37R4259990
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	108.6	109	110	107
2	Boot Lid	100.3	97	105	99
3	Roof	93.3	97	89	88/100
4	Left Front Fender	94.3	92	90	101
5	Left Front Door	93.3	95	92	94
6	Center Panel Left				
7	Left Rear Door	103.9	109	108	95
8	Left Back Panel	106.6	109	104	107
9	Right Front Fender	96.1	97	97	95
10	Right Front Door	96.0	98	97	93
11	Center Panel Right				
12	Right Rear Door	99.4	103	98	98
13	Right Back Panel	110.0	116	104	110

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Floor Mat - Worked - Small / (R) Front Floor Mat - Missing - Yes</p>	<p>Remarks (L) Front Door, Molding - Scratch - Medium / (L) Rear Door, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / (R) Front Door, Molding - Scratch & Dent - Minimal / (R) Rear Door, Molding - Scratch - Medium / (R) Rear Fender, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / Roof - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>With LTO plate and warranty booklet, No Tools and Jack and Sparetire, No spare key and scratch headlight and tail light.</p>