

## General Information

Date & Time: 08, Oct, 2025 18:40

<b>Make</b>	Toyota	<b>Model</b>	Vios
<b>YOM</b>	2025	<b>Odo Meter Reading</b>	19,119
<b>Registration No.</b>	DBQ4570	<b>Chassis No.</b>	PA1B18F39R4269517
<b>CC</b>	1.3	<b>Transmission</b>	CVT
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Blue		

## Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	112.6	112	115	111
2	Boot Lid	110.6	109	110	113
3	Roof	103.5	105	96	101/112
4	Left Front Fender	96.8	100	94	97
5	Left Front Door	106.0	103	104	111
6	Center Panel Left				
7	Left Rear Door	104.0	104	106	102
8	Left Back Panel	111.3	108	115	111
9	Right Front Fender	100.3	95	99	107
10	Right Front Door	101.6	104	100	101
11	Center Panel Right				
12	Right Rear Door	104.8	97	106	111
13	Right Back Panel	112.3	109	110	118

## Overall Evaluation :

**B**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="color: red; font-weight: bold; font-size: 1.2em;">C</span>	<b>Exterior Evaluation :</b> <span style="color: red; font-weight: bold; font-size: 1.2em;">C</span>
 <p><b>a :</b> Cut, Fray <b>d :</b> Loose, Deformed <b>k :</b> Animal Hair <b>s :</b> Smell <b>t :</b> Cigarette Burns <b>x :</b> Defective <b>y :</b> Stain</p>	 <p><b>A :</b> Scratch <b>AU :</b> Scratch &amp; Dent <b>B :</b> Modified <b>C :</b> Corrosion <b>G :</b> Stone chip <b>P :</b> Faded <b>S :</b> Rust <b>SC :</b> Rust &amp; Corrosion <b>U :</b> Dent <b>X :</b> Defective <b>Y :</b> Crack, Gap</p>
<p><b>Remarks</b> Rear Seat - Grime - Medium / Mat Other - Grime - Large / (R) Front Seat - Grime - Small / (L) Front Trim - Grime - Small / (L) Front Floor Mat - Worked - Large / (L) Front Trim - Worked - Small</p>	<p><b>Remarks</b> (R) Front Door, Molding - Dent - Small / Rear Bumper, Lamps, Panels - Scratch &amp; Dent - Small / (L) Front Door, Molding - Scratch &amp; Dent - Small / Front Bumper, Grille, Lamps - Scratch - Large / (R) Front Fender, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch - Medium / Bonnet, Headlight - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal</p>
<b>Frame Evaluation :</b> <span style="color: red; font-weight: bold; font-size: 1.2em;">A</span>	<b>Functional Evaluation :</b> <span style="color: red; font-weight: bold; font-size: 1.2em;">A</span>
<p><b>Remarks</b> Defects not found</p>	<p><b>Remarks</b> Lamps (Brake, Tail, Fog) - Issue - Yes / Horn - Issue - Yes / Spare Key - Issue - Unexist</p>

<p><b>Inspector Notes</b></p>
<p>foglight issue/ no tools and sparetire/ with jack and LTO plate/with warranty booklet/</p>