

General Information

Date & Time: 13, Oct, 2025 12:34

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	6,057
Registration No.	DBQ9526	Chassis No.	PA1B18F37R4274005
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	113.3	116	114	110
2	Boot Lid	116.3	111	119	119
3	Roof	100.3	111	100	95/96
4	Left Front Fender	101.3	102	100	102
5	Left Front Door	107.0	105	108	108
6	Center Panel Left				
7	Left Rear Door	105.6	106	106	105
8	Left Back Panel	112.3	120	113	104
9	Right Front Fender	103.4	104	98	108
10	Right Front Door	103.0	100	107	102
11	Center Panel Right				
12	Right Rear Door	108.3	110	107	108
13	Right Back Panel	119.3	107	111	140

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
	
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Floor Mat - Missing - Yes / (R) Front Trim - Grime - Minimal / Trunk Room - Worn, Scratch, Cut, Crack - Small / Rear Seat - Grime - Medium / (L) Front Seat - Grime - Small / Dashboard - Traces of Adhesive Tape - Yes / (L) Front Trim - Grime - Medium / Ceiling - Grime - Small	Remarks Rear Bumper, Lamps, Panels - Scratch - Small / (R) Rear Fender, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / Bonnet, Headlight - Rust, Corrosion - Medium / Front Bumper, Grille, Lamps - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Medium / (R) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / Roof - Dent - Minimal / Trunk Hood, Rear Gate - Scratch - Medium
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist

Inspector Notes
with LTO plate/with spare tire/No spare key/with jack and incomplete tools/with reverse camera/with warranty booklet/front right side floor mat missing