

General Information

Date & Time: 10, Oct, 2025 19:09

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	17,545
Registration No.	DBS8955	Chassis No.	PA1B18F36S4283011
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	114.6	124	106	114
2	Boot Lid	111.1	100	124	110
3	Roof	97.4	101	95	94/100
4	Left Front Fender	103.3	103	104	103
5	Left Front Door	101.0	100	101	102
6	Center Panel Left				
7	Left Rear Door	101.2	108	100	96
8	Left Back Panel	102.6	104	100	104
9	Right Front Fender	104.6	102	107	105
10	Right Front Door	96.1	96	93	99
11	Center Panel Right				
12	Right Rear Door	111.0	107	113	113
13	Right Back Panel	112.3	101	107	129

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Large / (R) Front Seat - Grime - Large / (L) Front Floor Mat - Worked - Large	Remarks Front Bumper, Grille, Lamps - Scratch & Dent - Large / (R) Rear Door, Molding - Dent - Small / (R) Rear Fender, Molding - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Medium / (L) Rear Fender, Molding - Scratch - Large / (L) Front Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes

with warranty booklet and LTO plate/ with spare tire and jack/ with tools