

General Information

Date & Time: 10, Oct, 2025 18:44

Make	Toyota	Model	Hilux Tamaraw
YOM	2025	Odo Meter Reading	787
Registration No.	DBU1939	Chassis No.	PAHACACA3S6423098
CC	2.4	Transmission	M/T
Fuel Type	Diesel	Type of Body	Utility Passenger
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	97.6	96	96	101
2	Boot Lid	47.5	47	51	45
3	Roof	119.5	121	121	109/127
4	Left Front Fender	96.9	99	98	94
5	Left Front Door	101.0	100	100	103
6	Center Panel Left				
7	Left Rear Door				
8	Left Back Panel	57.1	58	65	49
9	Right Front Fender	105.0	118	96	101
10	Right Front Door	99.0	96	100	101
11	Center Panel Right				
12	Right Rear Door				
13	Right Back Panel	49.0	48	46	54

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks (R) Front Door, Molding - Scratch - Minimal / (L) Side Gate - Scratch & Dent - Medium / Cargo Bed Floor - Scratch - Large
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes

with warranty booklet/ with sparetire and jack/ with tools with LTO plate