

General Information

Date & Time: 04, Oct, 2025 14:14

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	2,535
Registration No.	NEB9797	Chassis No.	PA1B18F32S4288657
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	138.3	118	148	149
2	Boot Lid	112.3	113	102	122
3	Roof	102.7	109	100	100/102
4	Left Front Fender	107.3	104	110	108
5	Left Front Door	110.0	103	123	104
6	Center Panel Left				
7	Left Rear Door	105.0	108	106	101
8	Left Back Panel	122.3	115	130	122
9	Right Front Fender	110.0	103	112	115
10	Right Front Door	105.3	106	106	104
11	Center Panel Right				
12	Right Rear Door	109.6	102	109	118
13	Right Back Panel	105.3	102	103	111

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : A
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks (L) Front Floor Mat - Worked - Small	Remarks (L) Front Fender, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Scratch - Minimal / Roof - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
With LTO plate and warranty booklet and Jack, No Tools and Sparetire.