

General Information

Date & Time: 10, Oct, 2025 15:58

Make	Toyota	Model	Vios
YOM	2023	Odo Meter Reading	52,090
Registration No.	NHI8932	Chassis No.	PA1B18F35P4209666
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	118.3	120	118	117
2	Boot Lid	120.6	123	118	121
3	Roof	95.9	104	89	90/101
4	Left Front Fender	96.4	103	91	95
5	Left Front Door	98.6	95	100	101
6	Center Panel Left				
7	Left Rear Door	98.4	100	96	100
8	Left Back Panel	107.6	109	104	110
9	Right Front Fender	99.3	93	102	103
10	Right Front Door	98.3	98	98	99
11	Center Panel Right				
12	Right Rear Door	106.3	109	105	105
13	Right Back Panel	109.3	113	106	109

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C		Exterior Evaluation : D	
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain		 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap	
Remarks Rear Seat - Grime - Large / (L) Front Seat - Grime - Large / (R) Front Seat - Grime - Large / (L) Front Floor Mat - Grime - Small		Remarks Member (Bolted) - Dent - Yes / Front Bumper, Grille, Lamps - Scratch & Dent - Large / (L) Rear Door, Molding - Dent - Small / (L) Front Fender, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Modified - Large / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / (R) Rear Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch & Dent - Small / (R) Front Fender, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch - Minimal	
Frame Evaluation : A		Functional Evaluation : A	
Remarks Defects not found		Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist	

Inspector Notes

no tools and nospare tire/ with warranty booklet and LTO plate/ with jack
