

General Information

Date & Time: 13, Oct, 2025 12:40

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	26,497
Registration No.	NHM8375	Chassis No.	PA1B18F31R4243686
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	109.6	120	109	100
2	Boot Lid	102.9	97	106	106
3	Roof	101.5	99	102	96/109
4	Left Front Fender	100.6	97	103	102
5	Left Front Door	104.6	102	111	101
6	Center Panel Left				
7	Left Rear Door	101.5	105	102	98
8	Left Back Panel	103.7	109	103	99
9	Right Front Fender	105.6	100	105	112
10	Right Front Door	108.6	102	115	109
11	Center Panel Right				
12	Right Rear Door	107.0	100	115	106
13	Right Back Panel	106.3	108	101	110

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Large / (R) Front Trim - Grime - Medium / (R) Front Seat - Grime - Large / (L) Front Seat - Grime - Medium / (L) Front Trim - Grime - Medium	Remarks (L) Front Fender, Molding - Dent - Medium / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Rear Door, Molding - Scratch - Minimal / (R) Front Door, Molding - Dent - Small / (R) Front Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Crack, Gap - Small / (L) Rear Fender, Molding - Scratch - Large / (L) Front Door, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
no spare tire/incomplete tools/ possible flooding/ scratches on tail light/ with jack and LTO plate/ with warranty booklet/