

General Information

Date & Time: 13, Oct, 2025 10:05

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	44,633
Registration No.	NHS3237	Chassis No.	PA1B18F37R4260816
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	112.3	110	109	118
2	Boot Lid	100.5	99	103	100
3	Roof	100.3	106	94	98/103
4	Left Front Fender	91.5	95	91	89
5	Left Front Door	100.3	97	99	105
6	Center Panel Left				
7	Left Rear Door	102.6	102	104	102
8	Left Back Panel	102.6	103	102	103
9	Right Front Fender	99.6	101	98	100
10	Right Front Door	108.6	112	110	104
11	Center Panel Right				
12	Right Rear Door	103.5	100	101	110
13	Right Back Panel	104.0	96	97	119

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Trim - Grime - Medium / (L) Front Seat - Grime - Medium / Rear Seat - Grime - Medium / (R) Front Seat - Grime - Small	Remarks Front Bumper, Grille, Lamps - Scratch & Dent - Large / (L) Front Door, Molding - Dent - Small / (R) Rear Door, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / (L) Rear Fender, Molding - Scratch - Medium / (L) Rear Door, Molding - Scratch - Medium
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes

Inspector Notes

with warranty booklet and LTO plate/ with jack and sparetire/ no tools