


General Information

Date & Time: 06, Oct, 2025 13:09

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	31,382
Registration No.	NHS1851	Chassis No.	PA1B18F36P4231188
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	117.6	121	119	113
2	Boot Lid	108.0	104	108	112
3	Roof	111.5	122	104	110/110
4	Left Front Fender	104.3	104	100	109
5	Left Front Door	106.6	108	105	107
6	Center Panel Left				
7	Left Rear Door	106.1	115	108	95
8	Left Back Panel	114.0	119	115	108
9	Right Front Fender	108.3	111	103	111
10	Right Front Door	105.0	109	101	105
11	Center Panel Right				
12	Right Rear Door	112.3	107	112	118
13	Right Back Panel	117.3	114	110	128

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Floor Mat - Missing - Yes / (R) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes</p>	<p>Remarks Rear Bumper, Lamps, Panels - Scratch & Dent - Large / Trunk Hood, Rear Gate - Scratch - Medium / (L) Rear Door, Molding - Scratch & Dent - Medium / Front Bumper, Grille, Lamps - Scratch & Dent - Medium / (R) Rear Door, Molding - Dent - Small / (R) Rear Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Small / Roof - Scratch - Minimal / Bonnet, Headlight - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>with LTO plate/ with spare tire and jack/ no tools and no warranty booklet/</p>