

General Information

Date & Time: 04, Oct, 2025 18:09

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	40,435
Registration No.	NHM6830	Chassis No.	PA1B18F30R4242835
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Green		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	108.7	116	99	111
2	Boot Lid	98.9	98	95	104
3	Roof	87.2	87	88	88/86
4	Left Front Fender	92.5	96	96	86
5	Left Front Door	92.9	95	90	93
6	Center Panel Left				
7	Left Rear Door	100.3	102	105	94
8	Left Back Panel	100.3	103	100	98
9	Right Front Fender	95.8	99	96	93
10	Right Front Door	96.2	93	98	99
11	Center Panel Right				
12	Right Rear Door	101.2	100	95	109
13	Right Back Panel	99.6	99	95	105

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Rear Seat - Grime - Medium / (R) Front Seat - Grime - Small / (L) Front Seat - Grime - Small / (L) Front Floor Mat - Grime - Medium / (R) Front Trim - Worked - Small / (R) Front Floor Mat - Worked - Large / (L) Front Trim - Grime - Small / Ceiling - Grime - Small / Overall Interior - Smell - Yes</p>	<p>Remarks (L) Front Fender, Molding - Dent - Medium / (L) Front Door, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / Member (Bolted) - Dent - Yes / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Small / Roof - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Crack, Gap - Small / (R) Front Fender, Molding - Scratch - Minimal / (R) Front Door, Molding - Scratch - Small / (R) Mirror - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>With LTO plate and warranty booklet , No Tools and Jack and Sparetire, No spare key and scratch headlight and tail light, Worn Tires and scratch wheel cover, foul smell, No reverse camera.</p>