

General Information

Date & Time: 04, Oct, 2025 18:10

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	10,250
Registration No.	CCG1570	Chassis No.	PA1B18F35R4279039
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	123.6	107	152	112
2	Boot Lid	107.6	103	107	113
3	Roof	96.6	90	99	89/109
4	Left Front Fender	96.6	99	96	94
5	Left Front Door	98.6	99	97	100
6	Center Panel Left				
7	Left Rear Door	97.1	99	97	96
8	Left Back Panel	111.0	114	113	106
9	Right Front Fender	101.8	97	103	106
10	Right Front Door	107.6	115	108	100
11	Center Panel Right				
12	Right Rear Door	112.0	112	111	113
13	Right Back Panel	107.3	107	103	112

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Floor Mat - Worked - Small / (L) Front Trim - Worked - Small / (R) Front Trim - Worked - Small</p>	<p>Remarks (L) Front Fender, Molding - Dent - Minimal / (R) Rear Fender, Molding - Scratch - Medium / (R) Rear Door, Molding - Dent - Minimal</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Defects not found</p>

<p>Inspector Notes</p>
<p>With LTO plate and warranty booklet, No Tools and Jack and Sparetire, Scratch headlight and tail light.</p>