

General Information

Date & Time: 06, Oct, 2025 15:00

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	24,938
Registration No.	NGC9713	Chassis No.	PA1B18F38RR4270898
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	113.6	114	107	120
2	Boot Lid	110.3	104	121	106
3	Roof	91.0	95	88	90/91
4	Left Front Fender	97.2	99	100	93
5	Left Front Door	102.5	97	103	108
6	Center Panel Left				
7	Left Rear Door	100.1	107	98	95
8	Left Back Panel	106.3	103	108	108
9	Right Front Fender	98.6	100	96	100
10	Right Front Door	100.5	101	102	99
11	Center Panel Right				
12	Right Rear Door	94.4	90	95	99
13	Right Back Panel	110.3	107	114	110

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : A
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Floor Mat - Worked - Small / (R) Front Floor Mat - Grime - Small / (L) Front Trim - Worked - Small</p>	<p>Remarks (L) Rear Door, Molding - Scratch - Small / Bonnet, Headlight - Dent - Minimal / Front Bumper, Grille, Lamps - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / Roof - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>With LTO plate and warranty booklet, No Tools and Jack and Sparetire, No spare key, Scratch headlight and tail light.</p>