

General Information

Date & Time: 14, Dec, 2024 10:43

Make	Toyota	Model	Vios
YOM	2023	Mileage	31,081
Registration No.	LAL8837	Chassis No.	PA1B18F3XN4193591
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	5.3	5	6	5
2	Boot Lid	4.5	5	4	5
3	Roof	4.1	4	4	4/4
4	Left Front Fender	4.3	4	4	4
5	Left Front Door	4.5	5	5	4
6	Center Panel Left				
7	Left Rear Door	4.2	4	4	4
8	Left Back Panel	4.5	5	5	4
9	Right Front Fender	4.3	4	4	4
10	Right Front Door	4.3	5	4	4
11	Center Panel Right				
12	Right Rear Door	4.2	4	4	5
13	Right Back Panel	4.2	4	4	5

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Grime - Small	Remarks Front Bumper, Grille, Lamps - Scratch - Medium / (R) Front Door, Molding - Scratch & Dent - Small / (R) Rear Door, Molding - Dent - Minimal / Trunk Hood, Rear Gate - Dent - Small / Rear Bumper, Lamps, Panels - Dent - Small / (L) Rear Door, Molding - Scratch - Medium / (L) Front Door, Molding - Scratch - Large / Roof - Dent - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes

with spare tire/tools/jack and warranty booklets/No reverse camera