

General Information

Date & Time: 06, Oct, 2025 14:55

Make	Toyota	Model	Vios
YOM	2022	Odo Meter Reading	27,426
Registration No.	DAQ1970	Chassis No.	PA1B18F37N4172651
CC	1.3	Transmission	M/T
Fuel Type	Gas	Type of Body	Sedan
Colour	Blackish Red Mica		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	112.6	104	110	124
2	Boot Lid	119.6	108	135	116
3	Roof	94.1	102	89	91/95
4	Left Front Fender	105.6	104	106	107
5	Left Front Door	109.3	105	104	119
6	Center Panel Left				
7	Left Rear Door	111.3	109	118	107
8	Left Back Panel	119.0	118	122	117
9	Right Front Fender	93.6	93	93	95
10	Right Front Door	99.0	101	93	103
11	Center Panel Right				
12	Right Rear Door	98.2	100	97	98
13	Right Back Panel	105.0	104	100	111

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	C	Exterior Evaluation :	E
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks (L) Front Floor Mat - Worked - Large / Rear Seat - Grime - Medium / (R) Front Floor Mat - Missing - Yes / Overall Interior - Smell - Yes / Ceiling - Grime - Small / Dashboard - Traces of Adhesive Tape - Yes / Glove Box - Loose, Deformed - Medium</p>		<p>Remarks (L) Rear Door, Molding - Scratch & Dent - Medium / (L) Front Door, Molding - Scratch & Dent - Medium / (L) Front Fender, Molding - Scratch & Dent - Large / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Mirror - Scratch - Minimal / Member (Bolted) - Dent - Yes / Front Bumper, Grille, Lamps - Scratch - Medium / Bonnet, Headlight - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Mirror - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Large / (R) Rear Fender, Molding - Scratch & Dent - Medium / Roof - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small</p>	
Frame Evaluation :	A	Functional Evaluation :	D
<p>Remarks Defects not found</p>		<p>Remarks Warning Lamps - Issue - Yes / Air Conditioner - Function - Weak / Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Wiper - Function - Weak / Horn - Issue - Yes / Spare Key - Issue - Unexist</p>	

Inspector Notes
<p>With LTO plate and Jack, No Tools and warranty booklet and Sparetire, No spare key, worn tires, adhesive marks on vehicle, worn tires, no reverse camera, foul smell, possible flooded, warning lamps on, no air-conditioned blower, dashboard missing parts.</p>