

General Information

Date & Time: 06, Oct, 2025 16:10

Make	Toyota	Model	Veloz
YOM	2024	Odo Meter Reading	11,441
Registration No.	CCA9467	Chassis No.	MHFAB1BYXR3107516
CC	1.5	Transmission	CVT
Fuel Type	Gas	Type of Body	SUV
Colour	Gray		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	107.0	97	118	106
2	Boot Lid	92.1	87	106	83
3	Roof	116.7	115	112	118/122
4	Left Front Fender	99.0	104	94	99
5	Left Front Door	114.6	110	115	119
6	Center Panel Left				
7	Left Rear Door	108.6	108	107	111
8	Left Back Panel	105.8	130	81	107
9	Right Front Fender	99.6	100	97	102
10	Right Front Door	111.6	116	110	109
11	Center Panel Right				
12	Right Rear Door	107.3	106	108	108
13	Right Back Panel	117.6	106	117	130

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : A
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks (L) Front Floor Mat - Worked - Small	Remarks (L) Front Fender, Molding - Dent - Small / (L) Front Door, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : C
Remarks Defects not found	Remarks Warning Lamps - Issue - Yes

Inspector Notes
With LTO plate and Sparetire and Jack and Incomplete Tools and warranty booklet, No spare key, warning lamps on.