

General Information

Date & Time: 06, Oct, 2025 19:46

Make	Toyota	Model	Innova
YOM	2024	Odo Meter Reading	25,287
Registration No.	CCC9249	Chassis No.	PA2JA8EM9R0142114
CC	2.8	Transmission	A/T
Fuel Type	Diesel	Type of Body	Wagon
Colour	Blackish Red Mica		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	102.7	95	110	103
2	Boot Lid	105.3	104	107	105
3	Roof	102.1	95	97	117/100
4	Left Front Fender	102.6	107	101	100
5	Left Front Door	106.6	105	110	105
6	Center Panel Left				
7	Left Rear Door	107.0	105	108	108
8	Left Back Panel	107.3	106	111	105
9	Right Front Fender	104.0	101	104	107
10	Right Front Door	106.0	102	110	106
11	Center Panel Right				
12	Right Rear Door	107.3	109	109	104
13	Right Back Panel	106.3	106	105	108

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : D
<div style="text-align: center; background-color: #cccccc; padding: 50px;">  No Image </div> <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<div style="text-align: center;">  </div> <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks Defects not found	Remarks (L) Front Fender, Molding - Scratch - Medium / Member (Bolted) - Dent - Yes / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Front Fender, Molding - Scratch - Large / (R) Front Door, Molding - Scratch - Large / (R) Rear Door, Molding - Scratch - Medium / Bonnet, Headlight - Scratch - Medium / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
With LTO plate and Sparetire and Jack and Incomplete Tools and warranty booklet, scratch headlight and tail light, matting missing,