

## General Information

Date & Time: 15, Jan, 2026 05:39

<b>Make</b>	Toyota	<b>Model</b>	Vios
<b>YOM</b>	2021	<b>Odo Meter Reading</b>	41,913
<b>Registration No.</b>	FAJ1619	<b>Chassis No.</b>	PA1B18F33M4156428
<b>CC</b>	1.3	<b>Transmission</b>	M/T
<b>Fuel Type</b>	Gas	<b>Type of Body</b>	Sedan
<b>Colour</b>	Green		

## Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	103.3	105	99	106
2	Boot Lid	116.0	109	120	119
3	Roof	92.5	98	91	84/98
4	Left Front Fender	93.4	93	93	95
5	Left Front Door	99.9	106	100	94
6	Center Panel Left				
7	Left Rear Door	102.4	107	99	101
8	Left Back Panel	102.7	110	96	102
9	Right Front Fender	88.9	88	88	90
10	Right Front Door	91.1	86	89	99
11	Center Panel Right				
12	Right Rear Door	95.0	86	102	97
13	Right Back Panel	97.1	93	96	103

## Overall Evaluation :

**D**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

<b>Interior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">D</span>	<b>Exterior Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">E</span>
<p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p>	<p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>
<b>Remarks</b> (R) Front Seat - Grime - Small / (R) Front Trim - Grime - Medium / (R) Rear Trim - Grime - Medium / Rear Seat - Grime - Medium / Trunk Room - Worn, Scratch, Cut, Crack - Small / (L) Rear Trim - Crinkle - Medium / (L) Front Trim - Grime - Medium / (L) Front Seat - Grime - Medium / Dashboard - Worn, Scratch, Cut, Crack - Small / Ceiling - Grime - Small / Console, Switchs, Vents - Worn, Scratch, Cut, Crack - Medium	<b>Remarks</b> (L) Mirror - Crack - Damaged / (L) Front Fender, Molding - Scratch & Dent - Small / Bonnet, Headlight - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Large / (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch & Dent - Small / (R) Step, In-panel, Side Spoiler - Dent - Small / (R) Rear Door, Molding - Scratch & Dent - Small / (R) Rear Fender, Molding - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Medium / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Large / (L) Step, In-panel, Side Spoiler - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / Roof - Dent - Medium
<b>Frame Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">A</span>	<b>Functional Evaluation :</b> <span style="float: right; color: red; font-weight: bold;">B</span>
<b>Remarks</b> Defects not found	<b>Remarks</b> Battery - Weak - Yes / Reverse Camera - N/A - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Seat Belts - Issue - Yes

<b>Inspector Notes</b>
with LTO plate/No spare tire/with 1 spare key/No jack and tools/No reverse camera/No warranty booklet/left side mirror issue/seatbelts issue/possible flooding/ tail light and brake light issue/floor mat front and back missing