

General Information

Date & Time: 17, Oct, 2025 16:50

Make	Toyota	Model	Vios
YOM	2022	Odo Meter Reading	21,384
Registration No.	FAN5392	Chassis No.	PA1B18F37N4183505
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	106.4	111	98	110
2	Boot Lid	105.3	100	102	114
3	Roof	92.2	93	87	91/98
4	Left Front Fender	94.6	100	94	90
5	Left Front Door	106.0	106	110	102
6	Center Panel Left				
7	Left Rear Door	101.1	105	103	96
8	Left Back Panel	104.6	106	105	103
9	Right Front Fender	93.1	89	96	95
10	Right Front Door	95.9	107	92	89
11	Center Panel Right				
12	Right Rear Door	93.3	92	90	99
13	Right Back Panel	94.0	99	90	93

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Grime - Small / (R) Front Trim - Grime - Small / (R) Front Floor Mat - Grime - Medium / (L) Front Trim - Grime - Medium / (L) Front Floor Mat - Worked - Small / Console, Switchs, Vents - Traces of Adhesive Tape - Yes</p>	<p>Remarks (L) Front Door, Molding - Scratch - Large / (L) Rear Door, Molding - Scratch - Large / (L) Front Fender, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Large / (R) Rear Door, Molding - Scratch - Large / (R) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>Right parklight busted. With warranty booklet, spare tire, jack and seat cover. Without tools. 1key. With LTO plate.</p>