

General Information

Date & Time: 13, Oct, 2025 19:20

Make	Toyota	Model	Rush
YOM	2022	Odo Meter Reading	25,461
Registration No.	FAN9313	Chassis No.	MHKE8FF3PNK046675
CC	1.5	Transmission	A/T
Fuel Type	Gas	Type of Body	SUV
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	108.4	112	99	114
2	Boot Lid	97.4	106	100	86
3	Roof	100.9	100	97	106/101
4	Left Front Fender	102.9	101	108	100
5	Left Front Door	112.6	113	110	115
6	Center Panel Left				
7	Left Rear Door	106.1	117	102	100
8	Left Back Panel	106.4	113	93	113
9	Right Front Fender	108.3	105	114	106
10	Right Front Door	104.0	108	102	102
11	Center Panel Right				
12	Right Rear Door	102.2	96	102	109
13	Right Back Panel	90.6	89	86	97

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Overall Interior - Smell - Yes / Overall Interior - Worn as per age - Yes / (R) Front Seat - Grime - Medium / (L) Front Seat - Grime - Medium / Mat Other - Missing - Yes / (R) Front Trim - Grime - Small / (L) Front Trim - Grime - Medium / (R) Rear Trim - Grime - Small / (L) Rear Trim - Grime - Small / Ceiling - Grime - Small / Rear Seat - Grime - Medium / Steering Wheel - Worn, Peel, Crack - Medium	Remarks (R) Front Fender, Molding - Scratch - Minimal / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Small / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Small / Bonnet, Headlight - Scratch - Medium / Roof - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Remote Key & Smart entry - Issue - Yes

Inspector Notes
no warranty booklet, no jack and tools, with spare tire, no LTO plate, possible flooding, scratches on tail light, smart key low battery