

General Information

Date & Time: 13, Jan, 2025 13:16

Make	Toyota	Model	Veloz
YOM	2023	Mileage	23,442
Registration No.	DBH1314	Chassis No.	MHFAB1BY9P3049749
CC	1.5	Transmission	CVT
Fuel Type	Gas	Type of Body	SUV
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	104.3	100	110	103
2	Boot Lid	106.1	108	121	90
3	Roof	109.0	114	115	100/107
4	Left Front Fender	111.6	105	112	118
5	Left Front Door	104.6	101	100	113
6	Center Panel Left				
7	Left Rear Door	106.3	110	104	105
8	Left Back Panel	117.6	127	113	113
9	Right Front Fender	106.0	105	109	104
10	Right Front Door	105.7	123	94	100
11	Center Panel Right				
12	Right Rear Door	104.5	106	100	108
13	Right Back Panel	122.6	107	125	136

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Cut, Crack - Small	Remarks (R) Rear Door, Molding - Scratch - Medium / (R) Rear Fender, Molding - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch - Medium / (L) Front Door, Molding - Scratch - Medium / (L) Rear Door, Molding - Scratch - Medium / (L) Rear Fender, Molding - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / Trunk Hood, Rear Gate - Scratch - Small
Frame Evaluation : A	Functional Evaluation : E
Remarks Defects not found	Remarks Retractable Mirror - Issue - Yes / Warning Lamps - Issue - Yes / Power Window (each) - Stuck, Gap - Yes / Door Lock - Issue - Yes / Sun Roof - Stuck, Gap - Yes / Power Seat - Issue - Yes / Power Steering - Issue - Yes / Shift Shock - Function - Weak / Air Conditioner - Function - Weak / Battery - Weak - Yes / Remote Key & Smart entry - Issue - Yes / Audio, Radio - Issue - Yes / Reverse Camera - N/A - Yes / Parking Brake - Function - Weak / Turn Signal, Hazard Flasher - Issue - Yes / Head Light, High Beam - Issue - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Wiper - Function - Weak / Horn - Issue - Yes / Spare Key - Issue - Unexist

Inspector Notes

no warranty booklet/ no tools/ not moving vehicle/ with LTO plate/with spare tire