

General Information

Date & Time: 13, Oct, 2025 19:17

Make	Toyota	Model	Vios
YOM	2023	Odo Meter Reading	59,911
Registration No.	FAQ1357	Chassis No.	PA1B18F33P4222495
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Green		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	103.8	109	99	103
2	Boot Lid	107.3	106	100	116
3	Roof	88.9	99	83	82/92
4	Left Front Fender	97.6	97	98	98
5	Left Front Door	99.1	104	99	95
6	Center Panel Left				
7	Left Rear Door	97.2	101	93	98
8	Left Back Panel	99.7	106	95	98
9	Right Front Fender	94.3	93	94	97
10	Right Front Door	95.7	98	98	92
11	Center Panel Right				
12	Right Rear Door	91.4	91	89	94
13	Right Back Panel	98.8	101	94	101

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Small / (R) Front Trim - Grime - Small / Mat Other - Grime - Small / (L) Front Trim - Grime - Small / (L) Front Floor Mat - Grime - Medium	Remarks Bonnet, Headlight - Scratch - Small / (R) Mirror - Scratch - Small / (R) Rear Door, Molding - Scratch & Dent - Large / (R) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Dent - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Small / Roof - Dent - Small / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Front Door, Molding - Dent - Small / (R) Front Fender, Molding - Scratch - Medium
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes

Without warranty booklet. With spare tire,jack and leather seat cover. Incomplete tools. 1 key. With LTO plate.