

## General Information

Date & Time: 14, Oct, 2025 20:58

|                  |         |                   |                   |
|------------------|---------|-------------------|-------------------|
| Make             | Toyota  | Model             | Wigo              |
| YOM              | 2024    | Odo Meter Reading | 15,275            |
| Registration No. | FAQ2145 | Chassis No.       | MHKAA1BC0PJ005319 |
| CC               | 1.0     | Transmission      | CVT               |
| Fuel Type        | Gas     | Type of Body      | Hatchback         |
| Colour           | Red     |                   |                   |

## Body / Panel Condition





| #  | Area               | Thickness(um) |        |        |          |
|----|--------------------|---------------|--------|--------|----------|
|    |                    | Average       | Value1 | Value2 | Value3/4 |
| 1  | Bonnet             | 106.0         | 100    | 108    | 110      |
| 2  | Boot Lid           | 79.9          | 72     | 81     | 87       |
| 3  | Roof               | 77.3          | 70     | 83     | 78/79    |
| 4  | Left Front Fender  | 85.7          | 83     | 83     | 91       |
| 5  | Left Front Door    | 101.6         | 96     | 98     | 111      |
| 6  | Center Panel Left  |               |        |        |          |
| 7  | Left Rear Door     | 89.3          | 100    | 90     | 78       |
| 8  | Left Back Panel    | 83.7          | 86     | 85     | 80       |
| 9  | Right Front Fender | 91.8          | 93     | 93     | 89       |
| 10 | Right Front Door   | 101.1         | 108    | 103    | 93       |
| 11 | Center Panel Right |               |        |        |          |
| 12 | Right Rear Door    | 98.8          | 95     | 97     | 105      |
| 13 | Right Back Panel   | 85.9          | 95     | 85     | 78       |

## Overall Evaluation :

**D**

### Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

| Interior Evaluation : <b>C</b>                                                                                                                                                                                                                     | Exterior Evaluation : <b>E</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
|  <p><b>a</b> : Cut, Fray <b>d</b> : Loose, Deformed <b>k</b> : Animal Hair <b>s</b> : Smell <b>t</b> : Cigarette Burns <b>x</b> : Defective <b>y</b> : Stain</p> |  <p><b>A</b> : Scratch <b>AU</b> : Scratch &amp; Dent <b>B</b> : Modified <b>C</b> : Corrosion <b>G</b> : Stone chip <b>P</b> : Faded <b>S</b> : Rust <b>SC</b> : Rust &amp; Corrosion <b>U</b> : Dent <b>X</b> : Defective <b>Y</b> : Crack, Gap</p>                                                                                                                                                                                                                                                                                                                                                                         |
| <p><b>Remarks</b><br/>Ceiling - Grime - Small / (R) Front Floor Mat - Grime - Medium / Mat Other - Grime - Medium / Trunk Room - Loose, Deformed - Large / (L) Front Floor Mat - Grime - Medium</p>                                                | <p><b>Remarks</b><br/>Bonnet, Headlight - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch &amp; Dent - Large / (R) Front Fender, Molding - Scratch - Large / (R) Front Door, Molding - Scratch - Large / (R) Mirror - Scratch - Small / (R) Rear Door, Molding - Scratch - Medium / (R) Rear Fender, Molding - Scratch &amp; Dent - Large / Rear Bumper, Lamps, Panels - Scratch &amp; Dent - Large / Trunk Hood, Rear Gate - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch &amp; Dent - Medium / (L) Front Door, Molding - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Small / (L) Front Fender, Molding - Scratch - Small</p> |
| Frame Evaluation : <b>A</b>                                                                                                                                                                                                                        | Functional Evaluation : <b>C</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                |
| <p><b>Remarks</b><br/>Defects not found</p>                                                                                                                                                                                                        | <p><b>Remarks</b><br/>Power Steering - Issue - Yes / Battery - Weak - Yes / Spare Key - Issue - Unexist</p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     |

## Inspector Notes

Low battery. Without warranty booklet, spare tire, jack and tools. With seat cover. 1 key. With LTO plate.