

General Information

Date & Time: 23, Oct, 2025 19:07

Make	Toyota	Model	Raize
YOM	2024	Odo Meter Reading	20,023
Registration No.	FAR8477	Chassis No.	MHKAA1BA6RJ125580
CC	1.0	Transmission	CVT
Fuel Type	Gas	Type of Body	SUV
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	150.0	146	154	150
2	Boot Lid	121.0	120	134	109
3	Roof	108.9	118	119	95/104
4	Left Front Fender	143.3	143	161	126
5	Left Front Door	140.6	138	144	140
6	Center Panel Left				
7	Left Rear Door	139.0	144	139	134
8	Left Back Panel	116.0	111	116	121
9	Right Front Fender	141.3	125	155	144
10	Right Front Door	142.6	153	138	137
11	Center Panel Right				
12	Right Rear Door	143.0	136	139	154
13	Right Back Panel	117.6	122	116	115

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Rear Seat - Grime - Large / (R) Front Seat - Grime - Large / (L) Front Seat - Grime - Large / (L) Front Floor Mat - Worked - Large</p>	<p>Remarks Front Bumper, Grille, Lamps - Scratch - Medium / (R) Front Fender, Molding - Scratch - Medium / (R) Rear Fender, Molding - Scratch - Medium / (R) Front Door, Molding - Scratch - Large / Bonnet, Headlight - Dent - Small / (R) Rear Door, Molding - Crack, Gap - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>maintenance warning / no jack no tools/ with spare tire and warranty booklet/ with LTO plate</p>