


General Information

Date & Time: 17, Oct, 2025 16:50

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	9,332
Registration No.	FAS8232	Chassis No.	PA1B18F36S4283221
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	102.0	102	96	108
2	Boot Lid	112.3	100	120	117
3	Roof	96.9	96	102	92/98
4	Left Front Fender	96.6	98	96	96
5	Left Front Door	98.6	97	106	93
6	Center Panel Left				
7	Left Rear Door	97.5	100	100	93
8	Left Back Panel	102.3	109	103	95
9	Right Front Fender	107.8	96	102	125
10	Right Front Door	101.0	105	99	100
11	Center Panel Right				
12	Right Rear Door	102.5	101	100	107
13	Right Back Panel	111.6	124	96	115

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Floor Mat - Worked - Small / (R) Front Floor Mat - Grime - Small / Rear Seat - Grime - Small / (R) Front Seat - Grime - Minimal / (L) Front Trim - Grime - Minimal</p>	<p>Remarks (R) Front Fender, Molding - Scratch & Dent - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Small / (R) Mirror - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium / Bonnet, Headlight - Scratch - Small / Roof - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Defects not found</p>

<p>Inspector Notes</p>
<p>with warranty booklet, with jack and tools, with spare tire, NO LTO plate, scratches on tail light</p>