

General Information

Date & Time: 14, Dec, 2024 14:02

Make	Toyota	Model	Veloz
YOM	2023	Mileage	40,293
Registration No.	NFE8414	Chassis No.	MHFAB1BY9N3024895
CC	1.5	Transmission	CVT
Fuel Type	Gas	Type of Body	SUV
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	102.6	100	101	107
2	Boot Lid	121.0	127	106	130
3	Roof	96.9	98	104	92/95
4	Left Front Fender	129.3	132	129	127
5	Left Front Door	105.3	105	101	110
6	Center Panel Left				
7	Left Rear Door	100.4	110	93	98
8	Left Back Panel	107.9	129	95	100
9	Right Front Fender	89.7	100	85	85
10	Right Front Door	132.6	135	130	133
11	Center Panel Right				
12	Right Rear Door	142.3	149	132	146
13	Right Back Panel	132.0	112	133	151

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Trim Other - Grime - Large	Remarks (R) Front Fender - Repair Traces - Yes / Rear Bumper, Lamps, Panels - Crack, Gap - Medium / (R) Rear Fender, Molding - Crack, Gap - Medium / (R) Front Door, Molding - Dent - Small / (L) Rear Fender, Molding - Crack, Gap - Medium / (L) Front Fender, Molding - Crack, Gap - Medium / Front Bumper, Grille, Lamps - Scratch - Medium / (R) Front Fender, Molding - Dent - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
no warranty booklet/ no tools/ with spare tire/ with jack