

General Information

Date & Time: 01, Dec, 2025 13:23

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	19,882
Registration No.	GBC2834	Chassis No.	PA1B23F32P6009199
CC	1.5	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	116.0	116	114	118
2	Boot Lid	106.3	105	101	113
3	Roof	101.8	101	114	93/100
4	Left Front Fender	95.3	97	92	97
5	Left Front Door	108.6	106	112	108
6	Center Panel Left				
7	Left Rear Door	112.6	117	112	109
8	Left Back Panel	114.3	117	108	118
9	Right Front Fender	101.0	100	100	103
10	Right Front Door	113.0	131	104	104
11	Center Panel Right				
12	Right Rear Door	113.6	108	113	120
13	Right Back Panel	119.3	114	118	126

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : D
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Worked - Small / Ceiling - Grime - Small / (R) Front Floor Mat - Grime - Small	Remarks (R) Front Fender, Molding - Scratch & Dent - Large / (R) Mirror - Scratch - Small / (R) Rear Door, Molding - Scratch & Dent - Large / (R) Front Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch & Dent - Medium / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / (L) Front Door, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Medium
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes

Inspector Notes
With warranty booklet, spare tire, jack, and leather seat cover. Incomplete tools. 2 keys. With LTO plate. Punctured spare tire.