


General Information

Date & Time: 05, Nov, 2025 21:42

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	13,768
Registration No.	GBD4747	Chassis No.	PA1B18F3XR4256405
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	104.8	115	91	108
2	Boot Lid	101.2	98	100	106
3	Roof	93.3	94	91	89/100
4	Left Front Fender	96.4	98	100	91
5	Left Front Door	92.0	97	88	91
6	Center Panel Left				
7	Left Rear Door	97.1	104	92	95
8	Left Back Panel	98.8	103	93	100
9	Right Front Fender	95.9	96	95	96
10	Right Front Door	92.1	94	89	94
11	Center Panel Right				
12	Right Rear Door	97.0	95	95	101
13	Right Back Panel	97.9	93	95	106

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Trim - Grime - Small / (R) Front Floor Mat - Grime - Small / (L) Front Trim - Grime - Small / (L) Front Floor Mat - Grime - Small / Ceiling - Grime - Small	Remarks (L) Mirror - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Large / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / (R) Rear Door, Molding - Scratch - Large / (R) Front Door, Molding - Scratch - Small / (R) Mirror - Scratch - Small / (R) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / Bonnet, Headlight - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : C
Remarks Defects not found	Remarks Power Steering - Issue - Yes / Battery - Weak - Yes

Inspector Notes

Without warranty booklet. With spare tire,jack and leather seat cover. Incomplete tools. 3 keys. With LTO plate.