

General Information

Date & Time: 26, Jan, 2026 10:10

Make	Toyota	Model	Veloz
YOM	2024	Odo Meter Reading	11,158
Registration No.	GBE5799	Chassis No.	MHFAB1BY6R3103916
CC	1.5	Transmission	CVT
Fuel Type	Gas	Type of Body	SUV
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	97.4	89	100	103
2	Boot Lid	99.0	96	105	96
3	Roof	115.5	131	129	101/101
4	Left Front Fender	100.0	100	94	106
5	Left Front Door	120.0	116	115	129
6	Center Panel Left				
7	Left Rear Door	107.0	109	106	106
8	Left Back Panel	119.0	125	120	112
9	Right Front Fender	98.6	107	99	90
10	Right Front Door	112.6	117	114	107
11	Center Panel Right				
12	Right Rear Door	105.6	105	102	110
13	Right Back Panel	122.6	110	120	138

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Floor Mat - Grime - Medium / (L) Front Trim - Grime - Small / (L) Rear Trim - Grime - Minimal / Mat Other - Grime - Small / Ceiling - Grime - Small / (R) Rear Trim - Grime - Minimal / (R) Front Floor Mat - Grime - Medium</p>	<p>Remarks (L) Front Fender, Molding - Scratch - Medium / (L) Mirror - Scratch - Small / (L) Front Door, Molding - Scratch - Medium / (L) Rear Door, Molding - Scratch - Medium / (L) Rear Fender, Molding - Scratch & Dent - Small / Trunk Hood, Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / (R) Rear Fender, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Mirror - Scratch - Small / (R) Front Fender, Molding - Scratch - Large / Front Bumper, Grille, Lamps - Scratch & Dent - Small / Roof - Scratch - Small</p>
Frame Evaluation : A	Functional Evaluation : C
<p>Remarks Defects not found</p>	<p>Remarks Warning Lamps - Issue - Yes / Battery - Weak - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>Oil deterioration/maintenance warning lamp. Without warranty booklet and tools. With spare tire, jack and seat cover. 1 key. No LTO plate.</p>