

General Information

Date & Time: 22, Jan, 2026 09:26

Make	Toyota	Model	Wigo
YOM	2021	Odo Meter Reading	12
Registration No.	HAC7657	Chassis No.	MHKA4DF5FLJ047449
CC	1.0	Transmission	A/T
Fuel Type	Gas	Type of Body	Hatchback
Colour	Orange		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	103.8	107	107	98
2	Boot Lid	109.0	110	117	100
3	Roof	90.0	83	99	91/87
4	Left Front Fender	108.0	108	112	104
5	Left Front Door	101.6	100	102	103
6	Center Panel Left				
7	Left Rear Door	107.6	109	105	109
8	Left Back Panel	104.0	106	105	101
9	Right Front Fender	109.3	106	110	112
10	Right Front Door	102.0	102	103	101
11	Center Panel Right				
12	Right Rear Door	102.3	102	103	102
13	Right Back Panel	112.3	108	113	116

Overall Evaluation :

D

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : D
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Trim - Grime - Medium / Sunvisor, Sunglass Holder - Grime - Medium / Ceiling - Grime - Large / (R) Front Trim - Grime - Small / Trunk Room - Loose, Deformed - Large</p>	<p>Remarks (L) Front Fender, Molding - Scratch - Small / (L) Front Door, Molding - Scratch & Dent - Large / (L) Rear Door, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Roof Spoiler, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / (R) Mirror - Scratch - Small / Roof - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / Member (Bolted) - Dent - Yes / Front Bumper, Grille, Lamps - Crack, Gap - Large / Bonnet, Headlight - Scratch - Minimal</p>
Frame Evaluation : C	Functional Evaluation : E
<p>Remarks Front Cross Member Support - Traces of Bending, or Marks of Panel Repair ? - Yes / Right Front Inside Panel (Front Side) - Traces of Bending, or Marks of Panel Repair ? - Yes / Left Front Inside Panel (Front Side) - Traces of Bending, or Marks of Panel Repair ? - Yes</p>	<p>Remarks Retractable Mirror - Issue - Yes / Warning Lamps - Issue - Yes / Panel, Meter - Issue - Yes / Power Window (each) - Stuck, Gap - Yes / Door Lock - Issue - Yes / Sun Roof - Stuck, Gap - Yes / Power Seat - Issue - Yes / Power Steering - Issue - Yes / Shift Shock - Function - Weak / Air Conditioner - Function - Weak / Power Steering Pump - Leak - Yes / Radiator Water Pump - Leak - Yes / Battery - Weak - Yes / Remote Key & Smart entry - Issue - Yes / Audio, Radio - Issue - Yes / Reverse Camera - N/A - Yes / Parking Brake - Function - Weak / Brake Pedal - Function - Weak / Turn Signal, Hazard Flasher - Issue - Yes / Head Light, High Beam - Issue - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes / Wiper - Function - Weak / Horn - Issue - Yes / Seat Belts - Issue - Yes / Spare Key - Issue - Unexist</p>

Inspector Notes

Non moving vehicle. Charging and starting issue. Cannot start even with new battery. Thermostat missing. Gap at front and rear bumper. Crack left taillight. Scratches on headlight and taillight. Rusted seat railings. Without warranty booklet and tools. With spare tire, jack and seat cover. 1 key. With LTO plate.