

General Information

Date & Time: 05, Nov, 2025 21:32

Make	Toyota	Model	Vios
YOM	2023	Odo Meter Reading	17,896
Registration No.	GAP2001	Chassis No.	PA1B18F31N4192412
CC	1.3	Transmission	M/T
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	104.6	102	104	108
2	Boot Lid	103.0	100	101	108
3	Roof	90.1	91	86	87/97
4	Left Front Fender	94.0	99	93	90
5	Left Front Door	103.5	106	113	92
6	Center Panel Left				
7	Left Rear Door	95.1	96	95	95
8	Left Back Panel	99.9	101	97	102
9	Right Front Fender	87.7	87	84	92
10	Right Front Door	91.8	94	87	95
11	Center Panel Right				
12	Right Rear Door	94.7	92	93	100
13	Right Back Panel	94.4	91	91	102

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (R) Front Floor Mat - Grime - Small / (R) Front Trim - Grime - Small / Ceiling - Grime - Minimal / (L) Front Trim - Grime - Small / (L) Front Floor Mat - Grime - Medium</p>	<p>Remarks (R) Rear Door, Molding - Scratch - Medium / (R) Rear Fender, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Fender, Molding - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / (L) Mirror - Scratch - Small / (L) Front Door, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Medium</p>
Frame Evaluation : A	Functional Evaluation : C
<p>Remarks Defects not found</p>	<p>Remarks Power Steering - Issue - Yes / Battery - Weak - Yes / Reverse Camera - N/A - Yes</p>

<p>Inspector Notes</p>
<p>With warranty booklet, spare tire, jack and spare tire. Without tools. 2 keys. NO LTO PLATE.</p>