

General Information

Date & Time: 24, Nov, 2025 14:19

Make	Toyota	Model	Vios
YOM	2023	Odo Meter Reading	17,683
Registration No.	GBA2405	Chassis No.	PA1B18F33P4224697
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	117.0	121	108	122
2	Boot Lid	116.0	108	123	117
3	Roof	106.3	98	103	115/109
4	Left Front Fender	105.6	109	106	102
5	Left Front Door	103.0	100	101	108
6	Center Panel Left				
7	Left Rear Door	112.3	124	107	106
8	Left Back Panel	114.3	129	104	110
9	Right Front Fender	108.3	110	106	109
10	Right Front Door	106.0	106	105	107
11	Center Panel Right				
12	Right Rear Door	111.6	113	105	117
13	Right Back Panel	112.3	111	105	121

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Ceiling - Grime - Small / (R) Front Floor Mat - Grime - Small / Mat Other - Grime - Small / (L) Front Floor Mat - Worked - Small</p>	<p>Remarks (R) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / (L) Rear Fender, Molding - Scratch - Small / (L) Rear Door, Molding - Scratch - Small / (L) Front Door, Molding - Scratch & Dent - Medium / Front Bumper, Grille, Lamps - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / Bonnet, Headlight - Scratch - Small / Roof - Scratch - Medium / Front Windshield - Scratch, Stone chip - Small</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>Scratch at front windshield. Without warranty booklet and tools. With spare tire, jack, and seat cover. 1 key. Temporary plate.</p>