

General Information

Date & Time: 09, Oct, 2025 14:46

Make	Mitsubishi	Model	Mirage
YOM	2024	Odo Meter Reading	21,490
Registration No.	NHG8201	Chassis No.	PAEA13TJRPA020243
CC	1.2	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Gray		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	128.6	131	124	131
2	Boot Lid	118.6	110	115	131
3	Roof	101.7	99	107	100/101
4	Left Front Fender	106.3	110	105	104
5	Left Front Door	111.0	111	110	112
6	Center Panel Left				
7	Left Rear Door	104.0	111	101	100
8	Left Back Panel	123.6	123	125	123
9	Right Front Fender	109.0	105	108	114
10	Right Front Door	110.0	108	109	113
11	Center Panel Right				
12	Right Rear Door	106.3	102	104	113
13	Right Back Panel	120.3	125	117	119

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Medium / (L) Front Floor Mat - Worked - Small / (R) Front Seat - Grime - Minimal / (L) Front Seat - Grime - Small / Rear Seat - Grime - Small	Remarks Rear Bumper, Lamps, Panels - Crack, Gap - Medium / (R) Front Door, Molding - Dent - Small / (L) Rear Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch & Dent - Small / (R) Front Fender, Molding - Scratch - Minimal / Bonnet, Headlight - Scratch - Small / (L) Mirror - Scratch - Minimal / Roof - Scratch & Dent - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
With LTO plate and Sparetire and Jack and Incomplete Tools and warranty booklet, scratch headlight and tail light, Worn Tires and Sparetire, No spare key.