

General Information

Date & Time: 10, Oct, 2025 12:33

Make	Mitsubishi	Model	Xpander
YOM	2025	Odo Meter Reading	10,894
Registration No.	NKC9779	Chassis No.	MK2LRNC1WSN00347
CC	1.5	Transmission	A/T
Fuel Type	Gas	Type of Body	Wagon
Colour	Gray		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	99.2	100	88	110
2	Boot Lid	89.7	92	89	89
3	Roof	98.0	92	103	97/100
4	Left Front Fender	94.5	95	92	97
5	Left Front Door	133.6	139	144	118
6	Center Panel Left				
7	Left Rear Door	95.6	97	99	91
8	Left Back Panel	99.2	99	100	99
9	Right Front Fender	88.5	87	91	88
10	Right Front Door	93.9	96	96	90
11	Center Panel Right				
12	Right Rear Door	92.6	88	97	93
13	Right Back Panel	94.0	84	99	99

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks Rear Seat - Grime - Medium / Dashboard - Traces of Adhesive Tape - Yes	Remarks (L) Front Fender, Molding - Scratch - Large / (L) Rear Door, Molding - Scratch - Large / (L) Rear Fender, Molding - Scratch - Medium / Trunk Hood, Rear Gate - Scratch - Medium / Rear Bumper, Lamps, Panels - Scratch - Large / (R) Rear Fender, Molding - Scratch - Large / (R) Rear Door, Molding - Scratch & Dent - Large / (R) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / (R) Front Door, Molding - Scratch - Medium / Front Bumper, Grille, Lamps - Scratch - Large / (R) Front Fender, Molding - Scratch & Dent - Small / Roof - Dent - Small
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes
no warranty booklet/ incomplete tools/ with LTO plate / with jack and spare tire