

General Information

Date & Time: 15, Oct, 2025 15:07

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	21,873
Registration No.	DBO6547	Chassis No.	PA1B18F31R4256874
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	110.6	103	120	109
2	Boot Lid	99.8	99	96	104
3	Roof	100.9	96	110	97/101
4	Left Front Fender	101.7	108	103	94
5	Left Front Door	135.3	115	142	149
6	Center Panel Left				
7	Left Rear Door	541.6	126	939	560
8	Left Back Panel	108.0	109	105	110
9	Right Front Fender	103.8	111	99	102
10	Right Front Door	98.5	99	96	100
11	Center Panel Right				
12	Right Rear Door	111.6	107	111	117
13	Right Back Panel	113.3	113	106	121

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Seat - Grime - Small / (L) Front Trim - Grime - Small / (L) Front Floor Mat - Cut, Crack - Medium / Dashboard - Traces of Adhesive Tape - Yes / (R) Front Seat - Grime - Large / Rear Seat - Grime - Medium / (R) Front Floor Mat - Grime - Large	Remarks (L) Front Door - Repair Traces - Yes / (L) Step - Repair Traces - Yes / (L) Rear Door - Repair Traces - Yes / (L) Rear Door, Molding - Repair mark - Yes / (L) Rear Door, Molding - Scratch & Dent - Large / (L) Rear Fender, Molding - Scratch & Dent - Medium / (L) Front Door, Molding - Scratch & Dent - Small / (L) Front Fender, Molding - Dent - Medium / Bonnet, Headlight - Dent - Medium / Front Bumper, Grille, Lamps - Scratch & Dent - Large / (R) Front Door, Molding - Scratch - Large / (R) Step, In-panel, Side Spoiler - Scratch - Small / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Repair mark - Yes / (L) Rear Fender, Molding - Repair mark - Yes / Trunk Hood, Rear Gate - Scratch & Dent - Small / Roof - Repair mark - Yes
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Turn Signal, Hazard Flasher - Issue - Yes / Lamps (Brake, Tail, Fog) - Issue - Yes

Inspector Notes
reverse light issue/ turn signal/hazard issue/ no tools/ with warrantybooklet and LTO plate/ with spare tire and jack/