

General Information

Date & Time: 17, Dec, 2024 06:08

Make	Toyota	Model	Veloz
YOM	2023	Mileage	29,385
Registration No.	CBT4141	Chassis No.	MHFAB1BYXN3044671
CC	1.5	Transmission	CVT
Fuel Type	Gas	Type of Body	SUV
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	99.9	98	101	101
2	Boot Lid	101.8	94	100	112
3	Roof	106.0	103	106	89/126
4	Left Front Fender	200.0	212	203	185
5	Left Front Door	146.0	151	142	145
6	Center Panel Left				
7	Left Rear Door	102.1	109	97	100
8	Left Back Panel	106.7	119	97	104
9	Right Front Fender	103.7	113	101	97
10	Right Front Door	104.3	104	103	106
11	Center Panel Right				
12	Right Rear Door	110.0	122	100	108
13	Right Back Panel	114.0	103	124	115

Overall Evaluation :

A

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : A	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Defects not found	Remarks (L) Front Fender - Repair Traces - Yes / (L) Front Fender, Molding - Repair mark - Yes / (R) Rear Door, Molding - Scratch - Large
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Spare Key - Issue - Unexist

Inspector Notes

with warranty booklet/ with spare tire, jack and tools