

General Information

Date & Time: 23, Oct, 2025 09:57

Make	Toyota	Model	Vios
YOM	2023	Odo Meter Reading	23,524
Registration No.	NHI8297	Chassis No.	PA1B18F34P4211053
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	109.0	123	101	103
2	Boot Lid	113.3	112	113	115
3	Roof	101.0	103	96	92/113
4	Left Front Fender	99.9	99	100	101
5	Left Front Door	97.7	100	98	95
6	Center Panel Left				
7	Left Rear Door	103.3	109	101	100
8	Left Back Panel	115.0	121	104	120
9	Right Front Fender	103.3	108	102	100
10	Right Front Door	100.6	101	100	101
11	Center Panel Right				
12	Right Rear Door	105.6	97	108	112
13	Right Back Panel	108.0	104	105	115

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Rear Seat - Grime - Medium / (R) Front Trim - Grime - Small / (R) Front Seat - Grime - Small / Trunk Room - Worn, Scratch, Cut, Crack - Small / (L) Front Trim - Grime - Small / (L) Front Seat - Grime - Minimal</p>	<p>Remarks Trunk Hood, Rear Gate - Repair Traces - Yes / Trunk Hood, Rear Gate - Dent - Medium / Rear Bumper, Lamps, Panels - Scratch - Medium / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Small / (R) Front Door, Molding - Scratch & Dent - Medium / (R) Rear Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Crack, Gap - Large / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Medium / Roof - Scratch & Dent - Small</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes</p>

<p>Inspector Notes</p>
<p>with LTO plate/No spare tire/No jack and tools/No reverse camera/with spare key/No warranty booklets/No VS FORM/HPG RECOVER WITH POSSIBLE HPG ALARM/lef and right front and rear window partially parts missing</p>