

General Information

Date & Time: 13, Oct, 2025 15:00

Make	Hyundai	Model	Accent
YOM	2021	Odo Meter Reading	35,522
Registration No.	DAP1660	Chassis No.	PEHC841BBMH009615
CC	1.4	Transmission	A/T
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	119.6	115	123	121
2	Boot Lid	101.1	104	91	108
3	Roof	127.7	133	118	120/140
4	Left Front Fender	99.8	97	94	108
5	Left Front Door	105.0	102	110	103
6	Center Panel Left				
7	Left Rear Door	99.1	100	96	102
8	Left Back Panel	94.9	103	85	97
9	Right Front Fender	122.6	119	129	120
10	Right Front Door	112.0	104	121	111
11	Center Panel Right				
12	Right Rear Door	109.3	121	102	105
13	Right Back Panel	113.0	101	107	131

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Floor Mat - Missing - Yes / (R) Front Floor Mat - Missing - Yes / Mat Other - Missing - Yes / Ceiling - Grime - Small / Rear Seat - Grime - Small</p>	<p>Remarks Front Bumper, Grille, Lamps - Crack, Gap - Medium / Bonnet, Headlight - Scratch - Small / (R) Front Fender, Molding - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Medium / (L) Rear Door, Molding - Scratch - Small / (L) Mirror - Scratch - Minimal / Roof - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Retractable Mirror - Issue - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>With LTO plate and Sparetire and Jack and Incomplete Tools, No warranty booklet, scratch headlight and tail light, no spare key,</p>