

General Information

Date & Time: 05, Nov, 2025 16:13

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	2,901
Registration No.	NKA7249	Chassis No.	PA1B18F37R4245667
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	125.3	115	134	127
2	Boot Lid	127.3	124	128	130
3	Roof	121.0	114	140	104/126
4	Left Front Fender	109.6	111	105	113
5	Left Front Door	149.3	130	162	156
6	Center Panel Left				
7	Left Rear Door	167.0	211	154	136
8	Left Back Panel	135.6	128	114	165
9	Right Front Fender	145.6	117	110	210
10	Right Front Door	127.6	114	143	126
11	Center Panel Right				
12	Right Rear Door	140.0	120	148	152
13	Right Back Panel	146.3	116	133	190

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : D
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
Remarks (L) Front Seat - Worn - Yes / (R) Front Seat - Grime - Minimal / Rear Seat - Grime - Medium / (L) Front Floor Mat - Worked - Small / (L) Front Trim - Grime - Minimal	Remarks (R) Front Fender - Repair Traces - Yes / (L) Front Fender - Repair Traces - Yes / (L) Rear Door - Repair Traces - Yes / Bonnet, Headlight - Scratch - Small / Front Bumper, Grille, Lamps - Dent - Small / (L) Front Fender, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Medium / (L) Rear Door, Molding - Scratch - Small / (L) Rear Fender, Molding - Scratch - Medium / Trunk Hood, Rear Gate - Repair mark - Yes / Trunk Hood, Rear Gate - Scratch - Medium / Roof - Scratch - Medium / (R) Front Door, Molding - Scratch & Dent - Minimal / (R) Rear Door, Molding - Scratch & Dent - Minimal / Front Bumper, Grille, Lamps - Repair mark - Yes / (R) Front Fender, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes

Inspector Notes
without manual and warranty booklet, with LTO plate, with jack but no tools, with spare tire, with back camera