

General Information

Date & Time: 15, Oct, 2025 18:08

Make	Toyota	Model	Vios
YOM	2025	Odo Meter Reading	30,007
Registration No.	DBR5546	Chassis No.	PA1B18F37R4274327
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	98.5	98	90	108
2	Boot Lid	97.6	90	98	105
3	Roof	85.5	91	81	82/89
4	Left Front Fender	92.9	96	94	90
5	Left Front Door	95.0	90	97	98
6	Center Panel Left				
7	Left Rear Door	90.2	93	89	89
8	Left Back Panel	101.2	103	101	100
9	Right Front Fender	92.9	94	90	95
10	Right Front Door	93.8	88	98	96
11	Center Panel Right				
12	Right Rear Door	93.3	98	94	88
13	Right Back Panel	99.9	97	92	111

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Rear Seat - Grime - Medium / (R) Front Trim - Grime - Minimal / (R) Front Seat - Grime - Medium / Trunk Room - Worn, Scratch, Cut, Crack - Small / (L) Front Floor Mat - Grime - Small / (L) Front Seat - Grime - Small / (L) Front Trim - Grime - Small / Ceiling - Grime - Small	Remarks (L) Front Door, Molding - Scratch - Medium / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Medium / Bonnet, Headlight - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Small / (R) Mirror - Scratch - Minimal / (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Small / (R) Rear Fender, Molding - Scratch - Small / Rear Bumper, Lamps, Panels - Scratch - Small / Trunk Hood, Rear Gate - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / Roof - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
with LTO plate/with spare tire/with spare key/with reverse camera/with jack and incomplete tools/No warranty booklets