


General Information

Date & Time: 15, Oct, 2025 07:54

Make	Toyota	Model	Fortuner
YOM	2022	Odo Meter Reading	19,803
Registration No.	NFH1173	Chassis No.	MHFCB8GS4M0523173
CC	2.4	Transmission	A/T
Fuel Type	Diesel	Type of Body	SUV
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	118.6	114	119	123
2	Boot Lid	102.6	98	108	102
3	Roof	112.2	107	116	109/117
4	Left Front Fender	112.0	113	122	101
5	Left Front Door	108.0	107	105	112
6	Center Panel Left				
7	Left Rear Door	107.4	108	115	99
8	Left Back Panel	112.3	120	107	110
9	Right Front Fender	114.0	121	108	113
10	Right Front Door	104.6	111	103	100
11	Center Panel Right				
12	Right Rear Door	104.0	109	103	100
13	Right Back Panel	116.3	118	110	121

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (R) Front Trim - Grime - Medium / (L) Rear Trim - Grime - Small / (L) Front Trim - Grime - Medium / Ceiling - Grime - Small	Remarks (R) Rear Door, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / (L) Step, In-panel, Side Spoiler - Scratch - Minimal / (L) Rear Door, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / (R) Front Fender, Molding - Dent - Medium / (R) Mirror - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Spare Key - Issue - Unexist

Inspector Notes

with LTO plate/with spare tire/with warranty booklet/with reverse camera/with jack and tools/No spare key