

General Information

Date & Time: 13, Oct, 2025 18:15

Make	Toyota	Model	Innova
YOM	2024	Odo Meter Reading	33,157
Registration No.	DBO7252	Chassis No.	PA2AA8EM5R0141736
CC	2.8	Transmission	A/T
Fuel Type	Diesel	Type of Body	Wagon
Colour	Silver		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	99.0	91	113	93
2	Boot Lid	100.3	108	97	96
3	Roof	93.4	90	87	100/97
4	Left Front Fender	93.8	95	94	93
5	Left Front Door	96.9	97	101	93
6	Center Panel Left				
7	Left Rear Door	93.8	93	100	89
8	Left Back Panel	94.2	95	93	95
9	Right Front Fender	106.3	104	108	107
10	Right Front Door	105.6	100	110	107
11	Center Panel Right				
12	Right Rear Door	106.6	110	103	107
13	Right Back Panel	106.0	106	102	110

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : A	Exterior Evaluation : B
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Floor Mat - Worked - Small / Ceiling - Grime - Small</p>	<p>Remarks Member (Bolted) - Dent - Yes / (R) Rear Fender, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal / Roof - Scratch & Dent - Minimal / (L) Rear Door, Molding - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Minimal / (R) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / Bonnet, Headlight - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Minimal</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>With LTO plate and Sparetire and Incomplete Tools, No warranty booklet and Jack, Scratch headlight and tail light, no spare key.</p>