

General Information

Date & Time: 12, Nov, 2025 17:35

Make	Toyota	Model	Vios
YOM	2023	Odo Meter Reading	22,259
Registration No.	CBE9403	Chassis No.	PA1B18F36N4199100
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Red Mica Metallic		

Body / Panel Condition



#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	107.0	105	108	108
2	Boot Lid	97.3	91	100	101
3	Roof	90.7	93	87	88/96
4	Left Front Fender	93.4	94	94	92
5	Left Front Door	106.0	103	107	108
6	Center Panel Left				
7	Left Rear Door	99.7	112	94	93
8	Left Back Panel	104.1	116	100	96
9	Right Front Fender	84.2	83	82	88
10	Right Front Door	90.3	94	90	87
11	Center Panel Right				
12	Right Rear Door	88.6	85	87	94
13	Right Back Panel	99.1	99	91	108

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : B
a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks Ceiling - Grime - Small / (R) Front Trim - Grime - Small / (R) Front Floor Mat - Grime - Small / (R) Front Seat - Grime - Medium / Rear Seat - Grime - Small / (L) Front Trim - Grime - Small / (L) Front Seat - Grime - Small	Remarks Bonnet, Headlight - Scratch - Small / (L) Front Fender, Molding - Dent - Small / (L) Mirror - Scratch - Minimal / (L) Step, In-panel, Side Spoiler - Scratch & Dent - Small / (R) Rear Fender, Molding - Dent - Small / Roof - Dent - Small / (R) Rear Door, Molding - Scratch & Dent - Small / Front Bumper, Grille, Lamps - Scratch - Small / (R) Mirror - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : B
Remarks Defects not found	Remarks Battery - Weak - Yes / Reverse Camera - N/A - Yes / Spare Key - Issue - Unexist

Inspector Notes

Crack right taillight. With waranty booklet,spae tire amd jack. Without tools and seat cover. 1 key. With LTO plate.