

General Information

Date & Time: 11, Nov, 2025 19:05

Make	Toyota	Model	Avanza
YOM	2025	Odo Meter Reading	16,048
Registration No.	FAR8740	Chassis No.	MHFAA1BY1R0029342
CC	1.3	Transmission	M/T
Fuel Type	Gas	Type of Body	MPV
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	101.1	98	99	106
2	Boot Lid	102.8	103	114	92
3	Roof	109.7	113	125	100/101
4	Left Front Fender	95.6	98	96	94
5	Left Front Door	107.0	100	108	113
6	Center Panel Left				
7	Left Rear Door	103.7	113	100	99
8	Left Back Panel	108.7	124	105	97
9	Right Front Fender	94.8	95	99	91
10	Right Front Door	108.0	115	108	101
11	Center Panel Right				
12	Right Rear Door	104.9	111	100	104
13	Right Back Panel	107.0	105	100	116

Overall Evaluation :

A

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation :	A	Exterior Evaluation :	B
			
<p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>		<p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>	
<p>Remarks (L) Front Floor Mat - Worked - Small / (R) Front Floor Mat - Grime - Small</p>		<p>Remarks Bonnet, Headlight - Scratch - Small / (L) Mirror - Scratch - Minimal / (L) Front Fender, Molding - Scratch - Small / (L) Front Door, Molding - Scratch - Small / (R) Rear Door, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch & Dent - Small / (R) Mirror - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / Front Bumper, Grille, Lamps - Scratch - Medium</p>	
Frame Evaluation :	A	Functional Evaluation :	C
<p>Remarks Defects not found</p>		<p>Remarks Warning Lamps - Issue - Yes / Battery - Weak - Yes / Spare Key - Issue - Unexist</p>	

Inspector Notes

Maintenance warning lamp. Without warranty booklet and tools. With spare tire,jack and seat cover. 1 key. With LTO plate.