

General Information

Date & Time: 28, Oct, 2025 10:46

Make	Toyota	Model	Wigo
YOM	2021	Odo Meter Reading	52,702
Registration No.	NGL8863	Chassis No.	MHKA4DF5FMJ053110
CC	1.0	Transmission	A/T
Fuel Type	Gas	Type of Body	Hatchback
Colour	White		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	80.9	84	83	76
2	Boot Lid	87.8	88	91	84
3	Roof	84.0	116	75	74/71
4	Left Front Fender	79.1	77	82	79
5	Left Front Door	80.3	79	84	79
6	Center Panel Left				
7	Left Rear Door	83.4	82	86	83
8	Left Back Panel	80.9	79	81	83
9	Right Front Fender	75.3	79	79	69
10	Right Front Door	79.8	78	81	81
11	Center Panel Right				
12	Right Rear Door	76.3	78	75	76
13	Right Back Panel	73.1	76	68	76

Overall Evaluation :

C

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : C	Exterior Evaluation : E
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks Console, Switches, Vents - Loose, Deformed - Large / Dashboard - Traces of Adhesive Tape - Yes / Overall Interior - Worn as per age - Yes / Steering Wheel - Worn, Peel, Crack - Small</p>	<p>Remarks Front Bumper, Grille, Lamps - Scratch & Dent - Large / (L) Front Fender, Molding - Crack, Gap - Medium / (L) Rear Fender, Molding - Scratch - Large / (L) Rear Door, Molding - Scratch - Large / (L) Front Door, Molding - Scratch & Dent - Small / Rear Bumper, Lamps, Panels - Scratch & Dent - Large / Trunk Hood, Rear Gate - Scratch - Small / (R) Rear Fender, Molding - Scratch - Large / (R) Rear Door, Molding - Scratch - Small / (R) Front Door, Molding - Scratch - Small / (R) Front Fender, Molding - Scratch - Small / (R) Mirror - Scratch - Medium / Bonnet, Headlight - Dent - Small</p>
Frame Evaluation : A	Functional Evaluation : A
<p>Remarks Defects not found</p>	<p>Remarks Audio, Radio - Issue - Yes / Spare Key - Issue - Unexist</p>

<p>Inspector Notes</p>
<p>possible flooding/ no jack and tools/ no warranty booklet/ with LTO plate and spare tire/</p>