

General Information

Date & Time: 05, Nov, 2025 11:10

Make	Toyota	Model	Vios
YOM	2024	Odo Meter Reading	4,000
Registration No.	EAJ3140	Chassis No.	PA1B18F35R4257848
CC	1.3	Transmission	CVT
Fuel Type	Gas	Type of Body	Sedan
Colour	Blue		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	107.2	122	100	100
2	Boot Lid	113.0	110	104	125
3	Roof	100.3	98	100	95/109
4	Left Front Fender	99.2	96	98	103
5	Left Front Door	109.3	123	107	98
6	Center Panel Left				
7	Left Rear Door	108.3	109	116	100
8	Left Back Panel	109.3	117	105	106
9	Right Front Fender	117.6	135	109	109
10	Right Front Door	102.0	104	102	100
11	Center Panel Right				
12	Right Rear Door	109.6	102	118	109
13	Right Back Panel	113.0	123	100	116

Overall Evaluation :

B

Disclaimer

This Grading Report provides a general assessment of the condition and appearance of the vehicle's interior, exterior, and frame. It does not constitute a comprehensive inspection report. The information contained herein reflects the vehicle's condition as of the date and time indicated. This report has been prepared by the company with the utmost care and diligence. However, the company assumes no responsibility for the accuracy or completeness of the information, as the vehicle is sold "as is" and "where is." Any disputes arising from this report shall not be subject to arbitration.

Interior Evaluation : B	Exterior Evaluation : B
 <p>a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain</p>	 <p>A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap</p>
<p>Remarks (L) Front Floor Mat - Worked - Small / (L) Front Seat - Worn - Yes / (R) Front Seat - Grime - Small / Rear Seat - Grime - Small / (R) Front Trim - Grime - Medium / (L) Front Trim - Grime - Minimal</p>	<p>Remarks (R) Front Door, Molding - Scratch - Minimal / (R) Rear Door, Molding - Scratch - Minimal / Trunk Hood, Rear Gate - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Small / Bonnet, Headlight - Scratch - Minimal / (L) Front Door, Molding - Scratch - Minimal / Roof - Scratch - Minimal / (L) Rear Fender, Molding - Scratch - Minimal / (L) Mirror - Scratch - Minimal / (R) Mirror - Scratch, Peeled - Minimal / (R) Front Fender, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / Rear Bumper, Lamps, Panels - Scratch - Minimal / (L) Rear Door, Molding - Dent - Small</p>
Frame Evaluation : A	Functional Evaluation : B
<p>Remarks Defects not found</p>	<p>Remarks Battery - Weak - Yes</p>

<p>Inspector Notes</p>
<p>with warranty booklet, with jack incomplete tools, with spare tire, with LTO plate, scratches on taillight</p>