

General Information

Date & Time: 18, Dec, 2024 10:39

Make	Toyota	Model	Innova
YOM	2021	Mileage	163,088
Registration No.	NGK3958	Chassis No.	PA2JA8EM0L0083560
CC	2.8	Transmission	A/T
Fuel Type	Diesel	Type of Body	Wagon
Colour	Black		

Body / Panel Condition





#	Area	Thickness(um)			
		Average	Value1	Value2	Value3/4
1	Bonnet	110.0	107	110	113
2	Boot Lid	96.6	102	96	92
3	Roof	93.0	101	84	94/93
4	Left Front Fender	94.6	92	93	99
5	Left Front Door	83.7	84	87	80
6	Center Panel Left				
7	Left Rear Door	95.1	88	89	108
8	Left Back Panel	264.3	380	183	230
9	Right Front Fender	94.2	90	102	91
10	Right Front Door	90.7	87	94	91
11	Center Panel Right				
12	Right Rear Door	92.3	86	95	96
13	Right Back Panel	95.5	97	89	101

Overall Evaluation :

B

Disclaimer

This Grading Report is intended to record the general appearance and condition of the interior, exterior & frame of the vehicle. This is not a detailed inspection report. This is issued on the date and time given herein and the company shall not be liable for the condition of the vehicle after this date and time. Any disputes regarding this report shall not be grounds for arbitration.

Interior Evaluation : B	Exterior Evaluation : C
 a : Cut, Fray d : Loose, Deformed k : Animal Hair s : Smell t : Cigarette Burns x : Defective y : Stain	 A : Scratch AU : Scratch & Dent B : Modified C : Corrosion G : Stone chip P : Faded S : Rust SC : Rust & Corrosion U : Dent X : Defective Y : Crack, Gap
Remarks (L) Front Floor Mat - Grime - Medium / Dashboard - Traces of Adhesive Tape - Yes	Remarks (L) Rear Fender - Repair Traces - Yes / (R) Front Fender, Molding - Scratch & Dent - Medium / (L) Rear Fender, Molding - Scratch & Dent - Large / Rear Bumper, Lamps, Panels - Scratch & Dent - Medium / Trunk Hood, Rear Gate - Scratch - Small / (L) Front Fender, Molding - Scratch - Minimal / Front Bumper, Grille, Lamps - Scratch - Medium / Roof - Dent - Small / (L) Front Door, Molding - Scratch - Minimal / (R) Rear Fender, Molding - Scratch - Minimal / (R) Step, In-panel, Side Spoiler - Dent - Minimal / Bonnet, Headlight - Scratch - Minimal
Frame Evaluation : A	Functional Evaluation : A
Remarks Defects not found	Remarks Defects not found

Inspector Notes
with spare tire/jack/tools and warranty booklet,